

Black suit coat had two longit. tears on collar (right side) just above the V cut on collar one round shaped hole or tear just below seam

Spectro Sample location Diagram



none of these holes or tears went through the backing material of the collar of the coat.

44-38861

Bulky 5586

PC-A5530

NECK TIE - Q 77



Spectro Samples
location Diagram